



Energy Center Unit Z


Primary Superheater Inlet Pendants Inspection Report

Spring Outage

Lead Inspector:
Area Inspectors:

Plant Engineer:

The Primary Superheater Inlet Pendants were counted boiler left to right (57 pendants) and tubes were counted from front to rear (16 tubes). In the SB-19 lane the last 3 tubes were shielded. Minor tube damage was noted at the bottom edge of the existing shields.



a



Primary Superheater Inlet Pendants (SB-19/REAR)

Priority 1

Item 1

There are (31) straight tubes experiencing moderate to severe sootblower erosion from SB-19 on the pendants listed below and 2 loops were severely eroded with UT's <60% remaining wall thickness.

Pendant	Tube	UT	Pendant	Tube	UT
2	4	0.124"	45	4	0.128"
7	6	0.123"	46	6	0.130"
10	5	0.127"	47	5	0.118"
11	6	0.125"	48	5	0.126"
11	7	0.130"	49	5	0.114"
13	4	0.124"	52	3	0.135"
18	4	0.128"	52	4	0.117"
19	7	0.128"	53	3	0.120"
23	4	0.135"	53	4	0.137"
24	5	0.130"	53	5	0.121"
25	4	0.108"	54	5	0.133"
25	4	0.140"	55	Loop #1-ISB	0.083"
27	4	0.130"	55	Loop #2-ISB	0.100"
27	5	0.134"	55	3	0.061"
31	5	0.130"	55	4	0.086"
32	5	0.087"	55	5	0.104"
32	6	0.125"	56	3	0.120"
38	5	0.077"	56	4	0.125"
39	4	0.124"	56	5	0.134"
40	6	0.128"	57	3	0.119"
42	4	0.131"	57	7	0.136"
43	5	0.131			

NOTE: Shields were previously installed on the last 3 tubes and some of the erosion on tube 3 was located directly under the shield.

Repair Recommendation: Once the alignment bar was removed and (32) areas of severe erosion was centered in the IK-19 lane. Install (30) 5' straight dutchman with location noted in table above.

Action Taken:



α




Primary Superheater Inlet Pendants (SB-19/REAR)

Priority 1

Item 2

There are (57) areas of moderate to severe sootblower erosion located on the underside of the rear alignment bar lugs were moderate on pendants 1-20 and severely eroded on pendant 21-57 (tube 16/last tube). This is due to the SB-19 lance channeling under alignment bar.

Note: The alignment bars were removed to gain access allowing additional inspections to be able to obtain a better depth of the SB erosion.



Repair Recommendation: Install (57) 2" x 2" padwelds on the rear of tube 16 (last tube) located underneath the alignment lugs due to IK -19.

Action Taken:




Primary Superheater Inlet Pendants (SB-14/FRONT)

Priority 1

Item 3

There are (12) areas experiencing moderate to severe sootblower erosion from (SB-14) located on the front side of the primary superheater inlet pendants at the roof (Scaffold level 4/Top). The thickness readings ranged from 0.154" to 0.107" of the original 0.220" MWT.

Pendants	Tb	UT	Repair/Comments
Scaffold Level # 4 (top)			
48	5	Eroded Hole in Shield	Install 36" Shield
49	5	Eroded Hole in Shield	Install 36" Shield
50	4	Eroded Hole in Shield	Install 36" Shield
51	3	0.107"	Install 4' dutchman
52	5	0.115"- 0.130"	Install 4' dutchman
53	3	Eroded Hole in Shield	Install 36" Shield
53	4	0.115"- 0.130"	Install 4' dutchman
56	3	Eroded Hole in Shield	Install 36" Shield
Scaffold Level # 2/3			
3	3	N/A	Install 4' dutchman
3	7	N/A	Install 4' dutchman
55	5	N/A	Install 4' dutchman
55	6	N/A	Install 4' dutchman



Tube Material: 2.25" O.D. x 0.220" MWT SA-210 A1

Repair Recommendation: Install (7) 4' dutchmen on the pendants listed in the table above. Install (5) 36" straight shield on the rear of tubes (3, 4, or 5) due to IK -14.

Action Taken:



Primary Superheater Inlet Pendants (SB-15 & SB-16 / FRONT)

Priority 1

Item 4


There are (5) areas / tubes experiencing moderate to severe sootblower erosion from (SB-15 & SB-16) located on the front side of the primary superheater inlet pendants (Scaffold level 2/3). The thickness readings appear to be <70% with lowest UT reading of 0.140" of the original 0.220" MWT.


Pendants	Tb	UT	Repair/Comments
Scaffold Level # 2/3			
3-25	7	Moderate / Severe Erosion (0.140")	Spread pendants to gain access.
49	3	0.164"	
51	3	N/A	
52	3-4	N/A	
53	3-5	N/A	

Tube Material: 2.25" O.D. x 0.220" MWT SA-210 A1

Repair Recommendation: Once the racked pendants are let loose call for a re-inspected.

Action Taken:





a

